National Transportation Safety Board	NTS	NTSB ID: NYC99LA200 Occurrence Date: 08/13/1999				Aircraft Registration Number: N193GE Most Critical Injury: Minor			
FACTUAL REPORT	Occ								
AVIATION	Occ	Occurrence Type: Accident				Investigated By: NTSB			
Location/Time									
Nearest City/Place	State	State Zip		Local Time		Time Zone			
HILLSBOROUGH	NH	03244		1311		EDT			
Airport Proximity: Off Airport/Airstrip	Distance F	nce From Landing Facility:				Direction From Airport:			
Aircraft Information Summary									
Aircraft Manufacturer		Model/Series					Type of Aircraft		
Cessna		208					Airplane		
Sightseeing Flight: No		Ai	ir Medical Transport Flight: No						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 13, 1999, at 1311 eastern daylight time, a Cessna 208, N193GE, was destroyed during a precautionary landing near Hillsborough, New Hampshire. The certificated airline transport pilot received minor injuries. Visual meteorological conditions prevailed for the ferry flight which departed from Manchester, New Hampshire (MHT), and was destined for Denver, Colorado (DEN). The flight was operated on an instrument flight rules flight plan under 14 CFR Part 91.

The pilot reported he flew the airplane to Bangor, Maine, on August 11, 1999, for the installation of two auxiliary fuel tanks. The installation took place on August 12 and 13, and the pilot flew the airplane to Manchester, Hampshire (MHT) where the auxiliary fuel tanks were filled. The Federal Aviation Administration (FAA), Portland Flight Standards District Office had issued a special flight permit for the overweight operation of the airplane.

At MHT, the airplane was serviced with 654 gallons of Jet-A. The wing tanks were filled, and the auxiliary fuel tanks (205 gallons each) were serviced with 190 gallons each, which brought them to within 1 inch of the top. The pilot reported that the gross weight of the airplane was about 10,000 pounds.

The takeoff and initial climb were without incident. As the airplane passed through about 800 to 900 feet, the pilot smelled turbine fuel. He stopped the climb and attempted to locate the source of the fumes. From his seat in the cockpit, he could not identify the source of the fumes. He requested radar vectors to the closest airport and initiated a descent. He then noticed about 1 inch of standing fuel on the floor of the cabin, and turned off the radios.

During the descent, the amount of fuel in the cockpit area continued to increase, so the pilot elected to land in an open field rather than continue toward the airport. He reported that due to fuel fumes and raw fuel in the cockpit, his vision was blurred, his eyes burned, and he had difficulty breathing. He positioned the airplane for landing into the wind. On final approach, the fuel was up over his ankles and his sectional charts were floating on top of the fuel.

After touchdown, he applied maximum reverse thrust and brakes. During the ground roll, at a speed of about 40 knots, he observed a ditch ahead of him. He had no further memory of events until he was being treated by paramedics.

A nearby airplane observed the landing and reported that the airplane nosed over during the landing roll. After about 5 minutes, the pilot exited the airplane and crawled away. About 5 minutes later, the airplane started to burn. Medical personnel arrived about 15 minutes after the accident.

An inspector from the FAA reported that the airplane traveled about 400 feet on the ground prior to encountering a ditch which measured about 60 feet wide and 3 feet deep. The airplane

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: NYC99LA200

Occurrence Date: 08/13/1999

Occurrence Type: Accident

Narrative (Continued)

crossed the ditch, and continued for about another 120 feet and came to rest. The nose landing gear had separated from the airplane. The airplane was consumed by fire except for the outboard wing panels and empennage.

Documents from the FAA and interviews with the pilot revealed the two tanks were mounted in the cabin laterally, and secured to the floor with tie-down straps. The takeoffs for the fuel lines were on the back side of the fuel tanks and not visible to the pilot. The two tanks fed into a common manifold, which was used to replenish the right wing fuel tank. The engine could not be fed directly from the auxiliary tanks. The pilot reported that he had not actuated the auxiliary tank system on the flight.

Examination of the supporting documents for the tank installation, furnished by the facility that performed the work, and interviews with the pilot, revealed the following; the fuel tanks were installed laterally; however, the FAA Form 337 showed the fuel tanks installed longitudinally; the instructions issued to the pilot for the use of the auxiliary tank system did not cover all contingencies, or limitations; the pilot reported that the 3 auxiliary fuel pumps used to transfer fuel from the auxiliary tanks to the right wing tank were secured to a platform. However, the platform was not secured to the airplane.

These items were discussed with the FAA Principle Maintenance Inspector (PMI) who had oversight authority for the facility that performed the auxiliary tank installation. The PMI reported that the facility has subsequently changed their procedures.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: NYC99LA200

Occurrence Date: 08/13/1999

AVIATION Occurrence Type: Accident												
Landing Facility/Approach Inf	formation											
Airport Name		A	Airport ID:	Airport Eleva	ition	Run	way Used	Runwa	y Lengt	h F	Runway Width	
				Ft	. MSL	0						
Runway Surface Type:		<u> </u>						<u> </u>				
Runway Surface Condition:												
Type Instrument Approach: NONE												
VFR Approach/Landing: Precaution	nary Landing											
Aircraft Information												
Aircraft Manufacturer		/Series						Number				
Cessna			208						2080	0193		
Airworthiness Certificate(s): Special Flight (Special)												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No	mebuilt Aircraft? No Number of Seats: 2				Certified Max Gross Wt.			8035 LBS Number			ines: 1	
				Engine Manufacturer: Model/Series: P&W PT6-114A							Rated Power: 600 HP	
- Aircraft Inspection Information												
Type of Last Inspection			Date of Last Inspection Time Sin			ince Last Inspection			Airframe	e Total Time		
AAIP			06/08/1999					79 Hours			6132 Hours	
- Emergency Locator Transmitter (F	ELT) Information								•			
ELT Installed? Yes	ELT Operate	ed? Yes		ELT Aided in Locating Accident Site? Yes								
Owner/Operator Information												
Registered Aircraft Owner			Street Address 13120 SW 63 RD AVE									
GREYSTOKE ENGINEERING	INC.		City							State	Zip Code	
				MIAMI						FL	33156	
Operator of Aircraft			Street Address 10800 E CACTUS ROAD #9									
RAM AERONAUTICAL			City							State	Zip Code	
			SCOTTSDALE AZ							AZ	85259	
Operator Does Business As: Operator Designator Code:												
- Type of U.S. Certificate(s) Held: N												
Air Carrier Operating Certificate(s):												
Operating Certificate:			Operator Certificate:									
Regulation Flight Conducted Under	r: Part 91: Genera	l Aviation	on									
Type of Flight Operation Conducted	l: Ferry											
]	FACTU	AL REPO	RT - AVIAT	ION						Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: NYC99LA200

Occurrence Date: 08/13/1999

A	ON		Occurrence												
First Pilot Inforr	mation														
Name						City			State	Date	of Birth	Age			
On File						On File	File On File C					47			
Sex: M Seat	Occupied:	Left	Pri	ncipal Profes	sion: Civiliar	n Pilot	ilot Certificate Number: On File								
Certificate(s):	Airlin	ne Transpor	t; Commerc	ial											
Airplane Rating(s): Multi-engine Land; Multi-engine Sea; Single-engine Land; Single-engine Sea															
Rotorcraft/Glider/L	TA: None	9													
Instrument Rating(s): Airplane															
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane															
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review?															
Medical Cert.: Cla	ss 1	Medica	al Cert. Statu	s: Valid Me	dicalno wa	ivers/lim.		Date of La	ast Medica	l Exam:	06/07/19	999			
								-							
- Flight Time Matri	Airplane Single Engine	Airplane Mult-Engine	Night	Inst Actual	rument Simulated	Rotorcra	aft	Glider	Lighter Than Air						
Total Time		10530	3000	7415	3091	667	1166	5 14	9						
Pilot In Command(P	IC)	10458	3000	7350	2991	650	1000)							
Instructor		800	100	500	300	20	100)							
Last 90 Days		168	123	123	45	2	11	ı	1						
Last 30 Days		22	22	22			4	1	_						
Last 24 Hours		1	1	1											
Seatbelt Used? Ye	es	Shou	lder Harness	Used? Yes		Toxic	Toxicology Performed? No Second Pilot? No								
Flight Plan/Itine	erary														
Type of Flight Plan	Filed: IFI	R													
Departure Point						State	e Air	oort Identifie	r De	parture ⁻	Time Zone				
MANCHESTER						NH		MHT		1300		EDT			
Destination						State	e Air	port Identifie	r						
DENVER						со									
Type of Clearance	: IFR					•	•		•						
Type of Airspace:	Class I	E													
Weather Inform	nation														
Source of Briefing		Service Stat	tion												
Method of Briefing	j:														
				FACTUAL	REPORT -	AVIATIO	N					Page 3			

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: NYC99LA200

Occurrence Date: 08/13/1999

Occurrence Type: Accident

	C1 1 BO.												
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevation	on	WOF Distance From Accident Site					Direction From Accident Site		
MHT	1300	EDT		234 Ft.	MSL		22 NM 120 Deg						. Mag.
Sky/Lowes	st Cloud Condition: Sca	ttered				•	3000 Ft.	AGL	Condition o	f Ligh	nt: Day		
Lowest Ce	iling: None			0 Ft.	AGL	Visib	oility:	7	SM	Altii	meter:	29.00	"Hg
Temperatu	ıre: 28 °C	Dew Point:		22 °C	Wind	Direction	: 170			Density Altitude:			Ft.
Wind Spee		Gusts:			Weath	ner Cond	tions at A	ccident S	Site: Visual C	L Cond	itions		
Visibility (F	RVR): 0 Ft	. Visibility	(RVV)	0	SM	Intensi	y of Prec	ipitation:	Unknown				
Restriction	s to Visibility: None												
Type of Pro	ecipitation: None												
Accident	Information												
Aircraft Dai	mage:		Air	Aircraft Fire:				Aircraft Exp	losio	n			
Classificati	on:												
- Injury Su	mmary Matrix	Fatal	Serious	Mino	r	None	TOTAL						
First Pi	lot				1			1					
Second	d Pilot												
Studen	t Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin A	Attendants												
Other C	Crew												
Passen	ngers												
- TOTAL A	ABOARD -				1			1					
Other 0	Ground	0	C)	0			o					
- GRANE	TOTAL -	0)	1			1					
		•											

TRANSPO	
National Transportation Safety Board	d
9 9 3 3	

FACTUAL REPORT AVIATION NTSB ID: NYC99LA200

Occurrence Date: 08/13/1999

Occurrence Type: Accident

							-			
/\	dm	ını	Ctr	つけい	10	Int	10ri	സവ	tιΛ	n
$\overline{}$	um	11 11	อแ	au	/ =	11111	OH	II a	แบ	ш

Investigator-In-Charge (IIC)

ROBERT L. HANCOCK

Additional Persons Participating in This Accident/Incident Investigation:

DONALD LEVESQUE FAA FSDO PORTLAND, ME